The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

For Jeff Tessoft. R13204-262-2721 AGA 679 May 77

CSV Whidbey Golf & Country Club

ADDRESS _____ PHONE _____

WELL LOCATION 2 NDI near Club house 6" Backup well

DEPTH 133 C.U. 117 10 S.L. 86 FLOW 2 GPM PFDD 60 +

SCREEN 3 Screens 16" [illegible] 2-10 [illegible] 1-[illegible] SS 17' 1" long Packer DRIVE SHOE _____

SURFACE SEAL Cement WELL CAP PLATE

DRILLER GARY WHIDBEY WELL DRILLERS

FORMATION	FROM	TO	OTHER INFORMATION	CASING LENGTHS			
Grind Clay		20		20	3		
Hard Pan	20	35		20	0	40	3
Sand	35	41		10	0	50	3
Sand Clay	41	65		20	1/2	70	3 1/2
Dry Sand	65	86		7	6	77	9 1/2
Wet Sand	86	133		10	0	87	9 1/2
				10	1/4	97	9 3/4
				10	0	107	
				10	1/4	117	10
				10	0	127	10
				10	0	137	10

DAILY FOOTAGE

RECEIVED
DEPARTMENT OF ECOLOGY
[illegible] 2012
WATER RESOURCES PROGRA
NWRO