~~WELL # 5 5 7 7 A~~ 33/1-2 B

File Original and First Copy with Department of Ecology
Second Copy — Owner's Copy
Third Copy — Driller's Copy

WATER WELL REPORT
STATE OF WASHINGTON

Application No.
Permit No. G1-24727

(1) OWNER: Name L K Ferguson Address 421 McClain · Silver Ton OR.

(2) LOCATION OF WELL: County Island Sec #1 NW ¼ NE ¼ Sec 26 T 33 N, R 1 E W.M.

Bearing and distance from section or subdivision corner Park Acres Sub Lot # 26

(3) PROPOSED USE: Domestic ☑ Industrial ☐ Municipal ☐ Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one)
New well ☑ Method: Dug ☐ Bored ☐
Deepened Cable ☑ Driven ☐
Reconditioned Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6" inches.
Drilled 228 ft. Depth of completed well 228 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6" Diam. from 0' ft. to 218 ft.
Threaded ☐ 5" Diam. from 223' ft. to 228 ft.
Welded ☑ " Diam. from ft. to ft.

Perforations: Yes ☐ No ☑
Type of perforator used
Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: Yes ☑ No ☐ Johnson
Manufacturer's Name
Type Model No.
Diam. 6" Slot size 25 from 218 ft. to 223 ft.
Diam. Slot size from ft. to ft.

Gravel packed: Yes ☐ No ☑ Size of gravel
Gravel placed from ft. to ft.

Surface seal: Yes ☑ No ☐ To what depth? 19+ ft.
Material used in seal Clay
Did any strata contain unusable water? Yes ☐ No ☑
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP: Manufacturer's Name
Type: H.P.

(8) WATER LEVELS: Land-surface elevation above mean sea level 291 ft.
Static level 211 ft. below top of well Date July 85
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☐ No ☑ If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Bailer test 8 gal./min with 0 ft. drawdown after 1½ hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes ☐ No ☐

(10) WELL LOG: (830' S & 520' E of N/4 cor-sec. 1)

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
0-3' top Soil	0'	3'
Hard Pan Gray in color	3'	44'
Clay with Sand - Gray in color	44'	91'
Sand with some clay Light Gray	91'	166'
Sand with small Rock Brown	166'	183'
Corse sand with small Rock Gray	183'	195'
Hard Pan	195'	218'
Sand with small Rocks	218'	223
Clay Gray in color	223'	228'

Well will yeald more Then 8 G.P.M. This is the only test I could make Accurately (Needs to Be Pump tested)

Work started July 19 85 Completed July 19 85

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Bedrock well Drillers (Person, firm, or corporation) (Type or print)

Address 150 W Troxel Rd. Oak Harbor Wash 98277

[Signed] Scott Statia (Well Driller)

License No. 1368 Date 7-26- 85

(USE ADDITIONAL SHEETS IF NECESSARY)

ECY 050 1-79

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.