Well tag id: ALQ 075

Start Card No. 037110

File Original and First Copy with Department of Ecology
Second Copy—Owner's Copy
Third Copy—Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Water Right Permit No. _____

(1) OWNER: Name A PEYSER Address 1287 E. HONEYMOON BAY Rd. GREENBANK 98253

(2) LOCATION OF WELL: County ISLAND NW ¼ NW ¼ Sec. 34 T. 30 N., R. 2 W

(2a) STREET ADDRESS OF WELL (or nearest address) Honeymoon Bay Rd.

(3) PROPOSED USE: [X] Domestic [ ] Irrigation [ ] DeWater [ ] Industrial [ ] Test Well [ ] Municipal [X] Other [ ]

(4) TYPE OF WORK: Owner's number of well (if more than one) _____

Abandoned [ ] New well [X] Deepened [ ] Reconditioned [ ]
Method: Dug [ ] Cable [X] Rotary [ ] Bored [ ] Driven [ ] Jetted [ ]

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 211 feet. Depth of completed well 211 ft.

(6) CONSTRUCTION DETAILS:

Casing Installed: 6" Diam. from 0 ft. to 201 ft.
Welded [X] 6" Diam. from _____ ft. to _____ ft.
Liner installed [ ] _____" Diam. from _____ ft. to _____ ft.
Threaded [ ] _____" Diam. from _____ ft. to _____ ft.

Perforations: Yes [ ] No [X]
Type of perforator used _____
SIZE of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes [X] No [ ]
Manufacturer's Name Johnson
Type STAINLESS Model No. _____
Diam. 6 Slot size 10 from 201 ft. to 206 ft.
Diam. 6 Slot size 10 from 206 ft. to 211 ft.

Gravel packed: Yes [ ] No [X] Size of gravel _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes [X] No [ ] To what depth? 18+ ft.
Material used in seal BENTONITE
Did any strata contain unusable water? Yes [ ] No [X]
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
Type: _____ H.P. _____

(8) WATER LEVELS: Land-surface elevation above mean sea level 180 - ft.
Static level 147 ft. below top of well Date MAY 90
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes [ ] No [X] If yes, by whom? _____
Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.
" " " "
" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____
Bailer test 10 gal./min. with 15 ft. drawdown after 2 hrs.
Airtest _____ gal./min. with stem set at _____ ft. for _____ hrs.
Artesian flow _____ g.p.m. Date _____
Temperature of water _____ Was a chemical analysis made? Yes [ ] No [ ]

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
HARD PAN	0	90
CLAY	90	108
DIRTY SAND	108	128
SANDY CLAY	128	157
VERY FINE SOUPY SAND	157	161
SANDY CLAY	161	200
WATER SAND	200	211

RECEIVED
MAY 14 1990
DEPT. OF ECOLOGY

RECEIVED
FEB 26 2008
DEPT. OF ECOLOGY

Work started MAY, 19__ Completed MAY 10, 19__

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME WHIDBEY DRILLERS (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address OAK HARBOR 98277

(Signed) [signature] (WELL DRILLER) License No. 129

Contractor's Registration No. WHIDBEY MAN Date MAY 10, 19__

(USE ADDITIONAL SHEETS IF NECESSARY)

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

The Dep. The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

File Original and First Copy with Department of Ecology
Second Copy—Owner's Copy
Third Copy—Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. 037110

Water Right Permit No. _____

(1) OWNER: Name A PEYSER Address 1287 E, Honeymoon Bay Rd, Greenbank 98253

(2) LOCATION OF WELL: County ISLAND NW ¼ NW ¼ Sec 34 T. 30 N., R. 2 W.M.

(2a) STREET ADDDRESS OF WELL (or nearest address) Honeymoon Bay Rd.

(3) PROPOSED USE: [X] Domestic [ ] Irrigation [ ] DeWater Industrial [ ] Test Well [ ] Municipal [X] Other [ ]

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
Abandoned [ ] New well [X] Deepened [ ] Reconditioned [ ]
Method: Dug [ ] Cable [X] Rotary [ ] Bored [ ] Driven [ ] Jetted [ ]

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 211 feet. Depth of completed well 211 ft.

(6) CONSTRUCTION DETAILS:
Casing installed: 6 " Diam. from 0 ft. to 201 ft.
Welded [X] _____ " Diam. from _____ ft. to _____ ft.
Liner installed [ ]
Threaded [ ] _____ " Diam. from _____ ft. to _____ ft.

Perforations: Yes [ ] No [X]
Type of perforator used _____
SIZE of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes [X] No [ ]
Manufacturer's Name Johnson
Type STAINLESS Model No. _____
Diam. 6 Slot size 10 from 201 ft. to 206 ft.
Diam. 6 Slot size 10 from 206 ft. to 211 ft.

Gravel packed: Yes [ ] No [X] Size of gravel _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes [X] No [ ] To what depth? 18+ ft.
Material used in seal Bentonite
Did any strata contain unusable water? Yes [ ] No [X]
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
Type: _____ H.P. _____

(8) WATER LEVELS: Land-surface elevation above mean sea level 180 - ft.
Static level 147 ft. below top of well Date May 90
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.))

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes [ ] No [X] If yes, by whom? _____
Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.
" " " "
" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____
Bailer test 10 gal./min. with 15 ft. drawdown after 2 hrs.
Airtest _____ gal./min. with stem set at _____ ft. for _____ hrs.
Artesian flow _____ g.p.m. Date _____
Temperature of water _____ Was a chemical analysis made? Yes [ ] No [ ]

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
HARD PAN	0	90
CLAY	90	108
DIRTY SAND	108	128
SANDY CLAY	128	157
VERY FINE Soupy SAND	157	161
SANDY CLAY	161	200
WATER SAND	200	211

RECEIVED
MAY 14 1990
DEPT. OF ECOLOGY

Work started May, 1990 Completed May 10, 1990

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME WHIDBEY DRILLERS (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)
Address OAK HARBOR 98277
(Signed) [signature] (WELL DRILLER) License No. 129
Contractor's Registration No. WHID289 MM Date May 10, 1990

(USE ADDITIONAL SHEETS IF NECESSARY)

ECY 050-1-20 (10/87) 1329 3