The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

Well tag id: AGA863 App # 12485

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY 61-60749P

WELL LOG

Record by Driller

Source Well Report

Location State of WASHINGTON

County Island

Area –

Map –

SW 1/4 SE 1/4 sec 15 T 29 N R 2 E

Diagram of Section

Drilling Co James L Bell

Address 5003 So E Harbor Rd Freeland Wa 98249

Method of Drilling Cable Date 19

Owner Whitney View Manor Comm Club

Address Rt #1 Box 842 Freeland Wa

Land surface datum — ft above/below —

SWL 138' Date May 67 19 Dims 8"x150'

Correlation	Domestic Material	From (feet)	To (feet)
	(Transcribe driller's terminology literally but paraphrase as necessary in parentheses. If material water bearing, so state and record static level if reported. Give depth in feet below land surface datum unless otherwise indicated. Correlate with stratigraphic column if feasible. Following log of materials, list all casings, perforations, screens, etc.)		
	Topsoil	0	1
	Sand, brown	1	41
	Hardpan, " , Sand, coarse, brown and gravel	41	46
	Sand, coarse, brown	46	54
	Sand, fine, brown	54	103
	Sand, Coarse, brown (W.B)	103	128
	Sand, Coarse, (W.B)	128	150
	Casing - 8'	0	150'
	Screen - Johnson Everdur		
	8" Slot size 15	140	150'
	Surface seal C 1 Asphalt ??	0	4'
	Pump - Pacific Sub 5-HP		
	Well Tests - Pump		
	Yield - 100 gpm w/ 6' DD @ 8 hrs		

Turn up Sheet of sheets

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WATER WELL REPORT

STATE OF WASHINGTON

Application No. [illegible]

Permit No. [illegible]

(1) OWNER: Name [illegible] Address [illegible] Freeland, WA 98249

(2) LOCATION OF WELL: County ISLAND

Bearing and distance from section or subdivision corner APPROX. 545 N, 75' [illegible] SW ¼ SE ¼ Sec. 15 T. [illegible] N., R. [illegible] W

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐ Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one) [illegible]

New well ☒ Method: Dug ☐ Bored ☐

Deepened ☐ Cable ☐ Driven ☐

Reconditioned ☐ Rotary ☒ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.

Drilled 150 ft. Depth of completed well 150 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6 " Diam. from 0 ft. to [illegible] ft.

Threaded ☐ " Diam. from ft. to ft.

Welded ☒ " Diam. from ft. to ft.

Perforations: Yes ☐ No ☒

Type of perforator used

SIZE of perforations in. by in.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

Screens: Yes ☐ No ☐

Manufacturer's Name [illegible]

Type [illegible] Model No.

Diam. [illegible] Slot size [illegible] from [illegible] ft. to [illegible] ft.

Diam. Slot size from ft. to ft.

Gravel packed: Yes ☐ No ☒ Size of gravel

Gravel placed from ft. to ft.

Surface seal: Yes ☐ No ☐ To what depth? [illegible] ft.

Material used in seal [illegible]

Did any strata contain unusable water? Yes ☐ No ☐

Type of water? Depth of strata

Method of sealing strata off

(7) PUMP: Manufacturer's Name [illegible]

Type: [illegible] H.P. [illegible]

(8) WATER LEVELS: Land-surface elevation above mean sea level [illegible] ft.

Static level [illegible] ft. below top of well Date [illegible]

Artesian pressure lbs. per square inch Date

Artesian water is controlled by [illegible] (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? Yes ☐ No ☐ If yes, by whom? [illegible]

Yield: gal./min. with ft. drawdown after hrs.

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level
[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]

Date of test [illegible]

Bailer test gal./min. with ft. drawdown after hrs.

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? Yes ☐ No ☐

(10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

528[illegible]

MATERIAL	FROM	TO
Top soil	[illegible]	[illegible]
Brown sand [illegible]	1	[illegible]
Brown [illegible]	[illegible]	[illegible]
Coarse [illegible]	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]
[illegible] sand	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]
Coarse brown sand	[illegible]	[illegible]
Coarse brown sand [illegible]	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]
[illegible]	[illegible]	[illegible]

ID 47594112282 1301

Work started [illegible] 19[illegible] Completed [illegible] 19[illegible]

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME [illegible] (Person, firm, or corporation) (Type or print)

Address [illegible]

[Signed] [illegible] (Well Driller)

License No. [illegible] Date [illegible] 19[illegible]

(USE ADDITIONAL SHEETS IF NECESSARY)

ECY 050-1-20 (Rev. 4-71)

App # 12485

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY 61-60°49P

WELL LOG

Record by Driller

Source Well Report

Location State of WASHINGTON

County Island

Area -

Map -

Sw 1/4 SE 1/4 sec 15 T 29 N R 2 E W

Diagram of Section

Drilling Co James L Bell

Address 5003 50 E Harbor Rd Freeland Wa 98249

Method of Drilling Cable Date 19

Owner Whitney View Manor Comm Club

Address Rt #1 Box 842 Freeland Wa

Land surface datum — ft above below —

SWL 138' Date May 67 19 Dims 8" x 150'

CORRELATION	Domestic MATERIAL	From (feet)	To (feet)
	Topsoil	0	1
	Sand, brown	1	41
	Hardpan, " , Sand, coarse, brown, and gravel	41	46
	Sand, coarse, brown	46	54
	Sand, fine, brown	54	103
	Sand, Coarse, brown (W.B)	103	128
	Sand, Coarse, (W B)	128	150
	Casing - 8'	0	150'
	Screen - Johnson Everdur		
	8" Slot size 15	140	150'
	Surface seal C I + asphalt "	0	4'
	Pump - Peerless 5.6 5 HP		
	Well Tests - Pump		
	Yield - 100 gpm w/ 6' DD @ 8 hrs		

(Transcribe driller's terminology literally but paraphrase as necessary in parentheses. If material water bearing so state and record static level if reported. Give depth in feet below land surface datum unless otherwise indicated. Correlate with stratigraphic column if feasible. Following log of materials list all casings perforations screens etc.)

Turn up Sheet of sheets

Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.