of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

WELL LOG

Record by: Driller
Source: Well Report

Location: State of WASHINGTON
County: Island
Area: –
Map: –
NW ¼ SE ¼ sec. 24 T 31 N., R. 2 E. ~~W.~~

Diagram of Section: 24

Drilling Co.: Kounkel
Address: 797 – 7 Smith Road Camano Is. Wa.
Method of Drilling: Cable Date 3-25-64, 19
Owner: East Lake Improvement Club Inc
Address: RFD #4, Box 939, Camano Is. Wa
Land surface, datum: 254 ft. above ~~below~~ SL
SWL: 242' Date 3-25-64, 19 Dims.: 6" x 317'

File number: 31, 2E, 24K

CORRELATION	Domestic MATERIAL	From (feet)	To (feet)
	Gravel	0	5'
	Hardpan	5	35'
	Clay, blue	35	55'
	Sand, brown, dry, hard	55	60'
	Sand, gray	60	75'
	Sand, brown, fine	75	140
	Clay, blue	140	195'
	Sand, brown	145	195'
	Clay, blue	195	245'
	Sand, clayey	245	250'
	Sand, coarse, (W.B)	250	255'
	Clay, blue	255	272'
	Sand, coarse, (W.B)	272	317

(Transcribe driller's terminology literally but paraphrase as necessary, in parentheses. If material water-bearing, so state and record static level if reported. Give depths in feet below land-surface datum unless otherwise indicated. Correlate with stratigraphic column, if feasible. Following log of materials, list all casings, perforations, screens, etc.)

Turn up (over) Sheet . of sheets

of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WELL LOG.—Continued No..... ..../.....-.....

CORRE-LATION	MATERIAL		From (feet)	To (feet)
		Depth forward	———	
	Casing: 6" Dia		0	205'
	8" Dia		0	307'
	Screen: Cook - Red brass			
	Dia: 6" Slot Size	30	307	317'
	Surface seal.	Mud	0	20'
	Pump: Peerless	Turbine	10 HP	
	Well Test:			
	Yield. 60 gpm w/ 3' DD @ 4 hrs.			
	Recovery:			
	0 — 245'			
	02' — 242'			
	25, March 1964			
	Temp H_2O - 50°			
	Chem. Analysis: Yes			

S. F. No. 7449—OS—(Rev 4-71)