File Original with Department of Ecology 129452
Second Copy Owner's Copy
Third Copy Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Notice of Intent W153703
UNIQUE WELL I D # ARO933
Water Right Permit No 32-3E-19F

(1) OWNER Name Michael-Rhonda Midthun Address 295 Grandview Ave, Camano Isl WA 98282

(2) LOCATION OF WELL County Island (15) SE 1/4 NW 1/4 Sec 19 T 32 N R 3E WM

(2a) STREET ADDRESS OF WELL (or nearest address) xxx D Jocup & Stillaquamish, Camano Isl WA 98282

TAX PARCEL NO R33219-368-1380

(3) PROPOSED USE ☒ Domestic ☐ Industrial ☐ Municipal ☐ Irrigation ☐ Test Well ☐ Other ☐ DeWater

(4) TYPE OF WORK Owner's number of well (if more than one)
☒ New Well ☐ Deepened ☐ Reconditioned ☐ Decommission
Method ☐ Dug ☐ Bored ☒ Cable ☐ Driven ☐ Rotary ☐ Jetted

(5) DIMENSIONS Diameter of well 6 inches
Drilled 104 feet Depth of completed well 104 ft

(6) CONSTRUCTION DETAILS
Casing Installed
☒ Welded 6 Diam from +2 ft to 95 ft
☐ Liner installed Diam from ft to ft
☐ Threaded Diam from ft to ft

Perforations ☐ Yes ☒ No
Type of perforator used
SIZE of perforations in by in
perforations from ft to ft

Screens ☒ Yes ☐ No ☒ K Pac Location 93
Manufacturer's Name Hilly
Type S Steel Model No
Diam 5 Slot Size 10 from 94 ft to 104 ft
Diam Slot Size from ft to ft

Gravel/Filter packed ☐ Yes ☒ No ☐ Size of gravel/sand
Material placed from ft to ft

Surface seal ☒ Yes ☐ No To what depth? 18 ft
Material used in seal Bentonite
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP Manufacturer's Name Goulds
Type 506 H P 2

(8) WATER LEVELS Land surface elevation above mean sea level ft
Static level 48 ft below top of well Date 3-20-03
Artesian pressure lbs per square inch Date 3-20-03
Artesian water is controlled by
(Cap valve etc)

(9) WELL TESTS Drawdown is amount water level is lowered below static level
Was a pump test made? ☒ Yes ☐ No If yes by whom? Gulliford-Pump
Yield 31 gal /min with 6 ft drawdown after 4 hrs
Yield gal /min with ft drawdown after hrs
Yield gal /min with ft drawdown after hrs
Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Bailer test gal /min with ft drawdown after hrs
Airtest gal /min with ft drawdown after hrs
Artesian flow g p m Date
Temperature of water Was a chemical analysis made? ☒ Yes ☐ No

(10) WELL LOG or DECOMMISSIONING PROCEDURE DESCRIPTION
Formation Describe by color character size of material and structure and the kind and nature of the material in each stratum penetrated with at least one entry for each change of information Indicate all water encountered

MATERIAL	FROM	TO
Top Soil	0	2
Br hard pan	2	19
cemented gravel	19	24
Dry sand-gravel	24	42
Dry sand	42	64
Br. clay	64	76
Dry sand-gravel	76	85
water-sand-gravel	85	104
This well meet all County-State rules & regulations at the time it was drilled		
Mere Hatt 3-4-03		

RECEIVED MAR 25 2003 DEPT OF ECOLOGY

RECEIVED APR 0 4 2003 DEPT OF ECOLOGY

Work Started 2-18-03 Completed 2-26-03

WELL CONSTRUCTION CERTIFICATION

I constructed and/or accept responsibility for construction of this well and its compliance with all Washington well construction standards Materials used and the information reported above are true to my best knowledge and belief

Type or Print Name License No
(Licensed Driller/Engineer)

Trainee Name License No
Drilling Company Genes Well Drilling
(Signed) Mere Hatt License No 0186
(Licensed Driller/Engineer)
Address 5115 268th N.W Stanwood, WA
Contractor s Registration No GENESWD071CC Date 3-22-03

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer For special accommodation needs contact the Water Resources Program at (360) 407 6600 The TDD number is (360) 407 6006

ECY 050-1 20 (11/98)

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.