The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

Seawater Intrusion Rating 'Low' Risk

WATER WELL REPORT
State of Washington

IC Site ID: 4VR
Start Card:
Water Right:

Unique Well ID
APH290

(1) OWNER: Name: Saunders Well — Address: 1921 Briarwood Dr Oak Harbor WA, 98277

(2) LOCATION OF WELL: Island: Whidbey — Township/Range-Section: 32N/01E-17N — Parcel Number: R13217-072-1340

(2a) Well Address 1921 BRIARWOOD DR (from parcel address — PWS-ID: 478940 — Source: 1 — PWS-Name: Saunders Well

(3) PROPOSED USE:

(4) TYPE OF WORK: Owner's Well Number (if more than one): 1

Method:

(5) DIMENSIONS: Diameter of Well: inches.

Drilled: feet. Depth of Completed Well: 158 ft.

(6) CONSTRUCTION DETAILS:

Casing Installed: Diam. (in) from to (ft)

Screens: Type Zone Diam Slot from to (ft)

Surface seal:
Material: To depth: ft.

(7) PUMP:
Type: Horsepower:

#Error Land-surface elevation (MSL): ft.

AvgWL Elevation: Calc'd Elev: 189 ft.

Earliest Level: ft. below toc Date:
Lastest Level: ft. below toc Date:
Average Level: ft. below toc Average Date:

(9) WELL TESTS:

Type	Yield	Drawdown	After	Date
	40 gpm	feet	hours	

(10) WELL LOG DESCRIPTION:

Material	From BGS	From MSL	Thick

Work Completed: TD Elev: 31 ft. MSL

WELL CONSTRUCTOR CERTIFICATION:

Name: Unknown
Address:
Contractor's Registration Number:

Remarks: No well log. Data obtained from DOH list.

Location Source: DGPS
North: 464279 East: 1540727
Latitd: 48 15.42938 Longit: 122 43.20491

Max CL: 75
Max NO3: 0.5

Generated by the Island County Hydrogeologic Database: 14-May-08

Disclaimer: Data presented has been collected from a variety of sources. Island County makes no guarantee as to the validity or accuracy of this data. Please report any errors to the Island County Hydrogeologist

32-1E-17N

WASHINGTON STATE DEPARTMENT OF ECOLOGY

Well Tagging Form

Unique Well Tag No: APH290

RECORD VERIFICATION (check ✓one)

☒ Well Report available (please attach this form to the well report and submit it to the Ecology Regional Office near you).
If a well report is not available, please complete a "Water Well Report for an Existing Well" form. This form is available at Ecology's headquarters office. **Do not use this form for wells that do not have a Water Well Report.**

WELL OWNERSHIP, IF DIFFERENT FROM WELL REPORT

First Name: Saunders Community Last Name: Well Association

Street Address: 1921 Briarwood Drive

City: Oak Harbor State: WA 98277

LOCATION OF WELL, IF DIFFERENT FROM WELL REPORT

Well Address: Parcel R13217-072-1340 (off Briarwood Drive)

City: Oak Harbor County: Island

T. 32 N. R. 1 E W.M. Sec. 17 SW ¼ of the SW

Latitude 48 16.42938 "

Longitude 122 43.20491 "

Elevation at land surface 189 feet/~~meters~~ (circle one)

SEE BACK SIDE OF PAGE...

RECEIVED
MAY 16 2008
DEPT. OF ECOLOGY

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WELL CHARACTERISTICS

Location of Well identification Tag: Strapped to well casing (inside well house)

D	C	B	A
E	F	G	H
M	L	K	J
N	P	Q	R

Scale 1:24,000 (1" = 2,000')

Indicate the location of the well within the Section by drawing a dot at that point

SECTION 17

COMMENTS:

See attached map for location



The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.