The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

6KK
R23130-338-3566
PWSID: 3451

# B & W DRILLING COMPANY

WATER WELL DRILLING
*Established 1959*
Serving South Whidbey
WALLY LEHMAN, Owner and Operator

ADVISORY SERVICE
COMMERCIAL & DOMESTIC WELL DRILLING
WELL REPAIRS
WELL TESTING
PUMP SALES & SERVICE

P.O. BOX 55
FREELAND, WASHINGTON
98249

PHONES
321-4016
321-4759
RADIO PHONE
321-1227

RECEIVED
DEC 7 1974
J. J. MILLEGAN & ASSOCIATES
SEATTLE, WASH.

ATTENTION: Mr. Bob Anderson

SUBJECT: Water Log for Mr. W. B. Hovis

| Depth | Layers |
|---|---|
| 0-5 | Top Soil |
| 5-38 | Hard Pan-Gray ( with rocks) |
| 38-45 | Clay-Blue |
| 45-62 | Clay-Brown |
| 62-74 | Hard Pan-Brown |
| 74-100 | Gravel ( loose) |
| 100-110 | Hard Pan-Soft |
| 110-260 | Rocks |
| 260-280 | Sand-Medium to Coarse (with water) |

| | | | |
|---|---|---|---|
| 5-7-74 DATE | W. B. Hovis NAME | | Greenbank PLACE |
| | ADDRESS | | 98253 ZIPPER |
| 6" WELL | 280' DEPTH | | 1-HP #8 PUMP |
| 260' STATIC | 5 G.P.M. | 275' DRAW DOWN | 275'-1" PIPE |
| 5 G.P.M. | B & W CO. | | 12-12-12 WIRE |
| 207' CASING | | | 2-#10 SSWO SCREEN |

RECEIVED
MAR 14 2008
DEPT OF ECOLOGY

28N/03E-01
475625122212401 (MIKE HOVIS COMMUNITY WATER)