The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

Welltagid: AGA832 #29 · 3E · 19G

WATER WELL REPORT
STATE OF WASHINGTON

Start Card No. [redacted]
Water Right Permit No.

(1) OWNER: Name SUN VISTA Address PO BOX 746 CLINTON, WA 98236-0746

(2) LOCATION OF WELL: County ISLAND - SW 1/4 NE 1/4 Sec 19 T 29 N., R 3E WM
(2a) STREET ADDRESS OF WELL (or nearest address) SUNLIGHT BCH HM OWNERS

(3) PROPOSED USE: MUNICIPAL

(4) TYPE OF WORK: Owner's Number of well (If more than one) 1
NEW WELL Method: ROTARY

(5) DIMENSIONS: Diameter of well 8 inches
Drilled 50 ft. Depth of completed well 50 ft.

(6) CONSTRUCTION DETAILS:
Casing installed: 8 " Dia. from +3.5 ft. to 36.5 ft.
WELDED " Dia. from ft. to ft.
" Dia. from ft. to ft.

Perforations: NO
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: YES
Manufacturer's Name HOWARD SMITH
Type STAINLESS STEEL Model No. KO
Diam. 8 slot size 20 from 35 ft. to 40 ft.
Diam. 8 slot size 15 from 40 ft. to 50 ft.

Gravel packed: NO Size of gravel
Gravel placed from ft. to ft.

Surface seal: YES To what depth? 18 ft.
Material used in seal BENTONITE
Did any strata contain unusable water? NO
Type of water? Depth of strata ft.
Method of sealing strata off

(7) PUMP: Manufacturer's Name GOULDS
Type SUBMERSIBLE H.P. 3

(8) WATER LEVELS: Land-surface elevation above mean sea level ... ft.
Static level 8.1 ft. below top of well Date 01/09/92
Artesian Pressure lbs. per square inch Date
Artesian water controlled by

(10) WELL LOG

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change in formation.

MATERIAL	FROM	TO
BROWN SAND & GRAVEL & WOOD	0	11
& CLAY	0	11
GRAY GRAVEL & CLAY	11	13
GRAY CLAY & SAND & GRAVEL	13	25
GRAY SAND & WATER	25	

Work started 01/07/92 Completed 01/09/92

(9) WELL TESTS: Drawdown is amount water level is lowered below static level.
Was a pump test made? YES If yes, by whom? DEAN JR/DOUG
Yield: 78.5 gal./min with 9.4 ft. drawdown after 1 hrs.
79.9 9.6 12
79.5 9.7 24

Recovery data

Time	Water Level	Time	Water Level	Time	Water Level
01.00	12.81	02.00	12.43	05.00	12.26
09.00	12.20	15.00	12.13	20.00	12.10
30.00	12.02	60.00	11.99	120.0	11.91

Date of test 02/11/92
Bailer test gal/min. ft. drawdown after hrs.
Air test 100 gal/min. w/ stem set at 33 ft. for 1 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? NO

WELL CONSTRUCTOR CERTIFICATION:
I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME HAYES DRILLING, INC.
(Person, firm, or corporation) (Type or print)

ADDRESS 556 ERSHIG RD. BOW, WA

[SIGNED] Steve Hillard License No. 762

Contractor's Registration No. HAYESDI106J5 Date 02/25/92

WELL SITE MEETS ALL SIGHTING CRITERIA UNDER I.C.C. 8.09 BASED ON 220
INFORMATION SUPPLIED BY THE OWNER OR WONER'S AUTHORIZED REPRESENTATIVE.

RECEIVED
MAR 09 1992
DEPT. OF ECOLOGY