Well tag id: AGA833

File Original and First Copy with Department of Ecology
Second Copy—Owner's Copy
Third Copy—Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. 200786
29/3/19 CL
Water Right Permit No.

(1) OWNER: Name SUN VISTA Sunlight Beach Property Owners Assoc. Address PO Box 746 CLINTON 98236

(2) LOCATION OF WELL: County ISLAND County NE ¼ NE ¼ Sec. 19 T. 29 N., R. 3E, W.

(2a) STREET ADDDRESS OF WELL (or nearest address) 0 FSW 1140 FNE 114

(3) PROPOSED USE: ☐ Domestic ☐ Irrigation ☐ DeWater Industrial ☐ Test Well ☐ Municipal ☑ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one)
Abandoned ☐ New well ☐ Deepened ☐ Reconditioned ☑ Method: Dug ☐ Cable ☑ Rotary ☐ Bored ☐ Driven ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 8" inches.
Drilled 31 feet. Depth of completed well 30'6" ft.

(6) CONSTRUCTION DETAILS:
Casing Installed: 8" " Diam. from 26' ft. to +3' ft.
Welded ☑ " Diam. from ft. to ft.
Liner installed ☐ " Diam. from ft. to ft.
Threaded ☐

Perforations: Yes ☐ No ☐
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: Yes ☑ No ☐
Manufacturer's Name Johnston
Type S.S. Model No.
Diam. 8" Slot size 12 from 20' ft. to 30'6" ft.
Diam. Slot size from ft. to ft.

Gravel packed: Yes ☐ No ☐ Size of gravel
Gravel placed from ft. to ft.

Surface seal: Yes ☐ No ☐ To what depth? ft.
Material used in seal
Did any strata contain unusable water? Yes ☐ No ☐
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP: Manufacturer's Name
Type: H.P.

(8) WATER LEVELS: Land-surface elevation above mean sea level 10' ft.
Static level 6'5" ft. below top of well Date 5/26/92
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☑ No ☐ If yes, by whom? Driller
Yield: 30 gal./min. with 2½ ft. drawdown after 24 hrs.

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Bailer test gal./min. with ft. drawdown after hrs.
Airtest gal./min. with stem set at ft. for hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes ☐ No ☐

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTI

Formation: Describe by color, character, size of material and structure, and a thickness of aquifers and the kind and nature of the material in each stratum penetra with at least one entry for each change of information.

MATERIAL	FROM	TO
ENGINEERED BY D.R. STRONG. CIVIL ENGINEER		
LAURIE BICKEL		
EXISTING WELL WAS -14'		
DEEP. DRILLED TO -24'		
CLEAN SAND GRAY	14'	24
SET SCREEN'S - 14-24'		
PUT 3' CHORLRIND SAND BOTTOM OF WELL - 14-11'		
FROM -11'- -7' CONCRETE		
-7' TO -1' COMPACTED		
FILL STRUCTUAL MATERIAL		
FROM -1' TO + 3' CONCRETE		
FROM -1' TO + 3' 12"		
CASING SET IN CONCRETE		
WITH CONCRETE BETWEEN		
8" AND 12" CASING		
8" CASING + 6' FROM		
OLD LEVEL OF WELL		

RECEIVED JUN 01 1992 DEPT. OF ECOLOGY

RECEIVED APR 01 2008 DEPT. OF ECOLOGY

Work started 5/16, 19. Completed 5/26, 19.

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this w and its compliance with all Washington well construction standar Materials used and the information reported above are true to my b knowledge and belief.

NAME Arnolds Plumbing & Septic Co. (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address 5489 So Coles Rd. Wa Langl

(Signed) Joe [illegible] (WELL DRILLER) License No. 0264

Contractor's Registration No. ARNOLPS099LC, Date 5-28, 19

(USE ADDITIONAL SHEETS IF NECESSARY)

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.