The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

PHONE ORANGE 8-4654 BOX 27

Mouse House

Statement
In Account With

WHIDBEY DRILLERS

June 11, 1964

Lambert Vander Stoep
OAK HARBOR, WASH.

Cmd John Woodall
Capt Tuttle

230 feet at $7.50 per foot	1725
one drive shoe	12
one screen with fittings & labor of installation	200
	1937
Stall Sales tax	77
	$2014

Dirn well is 140' (USGS Topo)

Log of Well drilled May 25 to June 11,

1' top soil then clay from 1' to 26' then sandy hard pan from 26 to 44, then sandy clay from 44 to 62, then clay from 62 to 118 (some sand mixed with the clay). Sandy clay from 118 to 143, then clay from 143 to 173, then sandy clay from 173 to 210, then clay from 210 to 222, then water in sand gravel formation. Well would make a little water at 26' depth, also from 118 to 143 and 173 to 210. Set No 20 slot screen with extension & bottom plug. Screen exposed to water formation from 225 to 230 foot levels. Used 224½ feet of casing. Static level 77 feet making 153 feet of water in well estimate 1000 gals per hr with 100 ft drawdo

77
177
230

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WASHINGTON STATE DEPARTMENT OF ECOLOGY

Well Tagging Form

Unique Well Tag No: APH 275

RECORD VERIFICATION (check ✓one)

☐ Well Report available (please attach this form to the well report and submit it to the Ecology Regional Office near you).
If a well report is not available, please complete a "Water Well Report for an Existing Well" form. This form is available at Ecology's headquarters office. **Do not use this form for wells that do not have a Water Well Report.**

WELL OWNERSHIP, IF DIFFERENT FROM WELL REPORT

First Name: Mouse House Water Association Last Name: PWS 11727

Street Address: 2

City: _____ State: _____

LOCATION OF WELL, IF DIFFERENT FROM WELL REPORT

Well Address: 2478 Matsen lane

City: Oak Harbor County: Island

T. 33 N. R. 02 E W.M. Sec. 35 SE ¼ of the SE

Latitude 48 17.93295 ' _____ "
Longitude 122 30.59801 ' _____ "

Elevation at land surface _____ feet/meters *(circle one)*

SEE BACK SIDE OF PAGE...

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WELL CHARACTERISTICS

Location of Well identification Tag: 6" casing next to well house.

D	C	B	A
E	F	G	H
M	L	K	J
N	P	Q	R

Scale 1:24,000 (1" = 2,000')

Indicate the location of the well within the Section by drawing a dot at that point

SECTION _____

COMMENTS:

R 23335-088-4850