The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

R23235-477-4290

(2) LOCATION OF WELL: County: ISLAND NE 1/4 SE 1/4 Sec 35 T 32N N, R 2E WM
(2a) STREET ADDRESS OF WELL (or nearest Address): 383 N. CAMANO RIDGE RD, CAMANO ISLAND

(3) PROPOSED USE: Domestic Industrial Municipal X
Irrigation
DeWater TEST WELL Other....

(4) TYPE OF WORK: Owner' No of Well if more than one: 1
Abandoned New Well..... X METHOD Dug... Bored.
Deepened..... Cable. Driven
Reconditioned Rotary X

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 380.00 Feet Depth of completed well 377.00 Ft.

(6) CONSTRUCTION DETAILS:
Casing Installed: Diam From Ft To Ft
Welded X 6 Diam From +1.5 Ft To 18.5 Ft
Liner Inst X 4 Diam From 5 Ft To 347 Ft
Threaded X

Perforations: NO
Types of perforator used
Size of perforations Inches, by Inches
Perforations from ft to
Perforations from ft to
Perforations from ft to

Screens: YES
Manufacturer's Name: SLOT WESTERN
Type: PVC Model No.
Diam 4 Slot size 20 From 347 Ft To 367 Ft
Diam 4 Slot size BLANK From 367 Ft To 377 Ft

Gravel packed: YES Size of gravel: 8-12
Gravel placed from: 300 Ft To: 380 Ft

Surface seal: YES To What Depth?: 18.5Ft
Material used in seal BENTONITE
Did any strata contain unusable water?: NO
Type of water: Depth of strata: Ft
Method of sealing strata off:

(7) PUMP: Manufacturer's Name: GOULDS
Type: SUB H.P. 3/4

(8) WATER LEVELS? Above mean sea level 520
Static Level 297 Ft. below top of well Date: 07/23/99
Artesian pressure Lbs. per square inch Date: / /
Artesian water is controlled by:

(9) WELL TESTS:
Drawdown is amount water level is lowered below static level
Was a pump test made?: YES If yes, by whom?: HIMEBAUGH DRILL
Yield: 4 Gal/min. with 43 Ft drawdown after 4 Hrs.
Yield: Gal/min. with Ft drawdown after Hrs.
Yield: Gal/min. with Ft drawdown after Hrs.
RECOVERY DATA
Time Water Level Time Water Level Time Water Level
SEE
CHARTS

Date of test / /
Bailer Test 4 gal/min with 35 ft. drawdown after 1 Hrs
Airtest gal/min with stem set at ft for Hrs
Artesian flow G.P.M. Date / /
Temperature of Water Was a chemical analysis made?: YES

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION:

Formation: Describe by color, character, size of material and show thickness of aquifers and the kind of nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
TOPSOIL	0	2
TILL BROWN	2	23
TILL BLUE	23	68
CLAY TAN	68	80
GRAVEL	80	90
SAND FINE WHITE	90	111
CLAY BLUE	111	124
ROCK	124	125
CLAY BLUISH GRAY 10% ROCK	125	250
SANDY	250	267
GRAVELY	267	
TAN CLAY	267	288
BLUE CLAY	288	335
ROCKY	335	340
COARSE SAND-FINE GRAVEL	340	347
FINE SAND	347	367
CLAY	367	380

THIS WELL FOLLOWS THE I.C.C.

809.07 C, D, & E AS LISTED WITH

THE ICMB.

SEE ATTACHMENT FOR PUMP TEST

Work Started 07/19/99 Work Completed 07/30/99

WELL CONSTRUCTOR CERTIFICATION:
I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to the best knowledge and belief.

Name: HIMEBAUGH DRILLING - BOYD HIMEBAUGH

Address: 828 B PORTAGE STREET, ARLINGTON, WA 98223

(Signed) [signature] License No 1877
Contractors
Registration
No. HIMEBDO99CX Date 08/20/99

RECEIVED
DEPARTMENT OF ECOLOGY

MAY 23 2012

WATER RESOURCES PROGRAM
NWRO