The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

91902 J 501
Island

ID 481715122324301

DOH 91902J 501

9-185
(October 1950)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

WELL SCHEDULE

Date 6-25, 1964 Field No 32/2-3M1
Record by B. D. N Office No
Source of data obs + owner

1 *Location* State WASH County ISLAND
Map DECEPTION PASS QUAD 1:62503
NW ¼ SW ¼ sec 3 T 32 N/S R 2 E/W
2 *Owner* LYNN [illegible] Address Reservation Rd NEAR
Tenant Address Polnell Rd
Driller VANDER STOEP Address OAK HARBOR
3 *Topography* Upland
4 *Elevation* 350 ft above/below MSL
5 *Type* Dug, drilled, driven, bored, jetted 3-5 1959
6 *Depth* Rept 187 ft Meas — ft
7 *Casing* Diam 6" in, to — in, Type ST
Depth 182 ft, Finish (Oslot screen) 182-181 ft
8 *Chief Aquifer* SAND From 175 ft to 187 ft
Others
9 *Water level* 156.75 ft rept./meas 6-25 1964 above/below Port
SANITARY SEAL which is — ft above/below surface
10 *Pump* Type S Capacity — G M —
Power Kind E Horsepower 3/4
11 *Yield* Flow — G M, Pump — G M, Meas, Rept Est
Drawdown little after — hours pumping Bailed 11 G M
12 *Use* Dom, Stock, PS, RR, Ind, Irr, Obs S
Adequacy, permanence
13 *Quality* — Temp — °F
Taste, odor, color — Sample Yes/No
Unfit for
14 *Remarks* (Log, Analyses, etc)

5'

W. Lt. = 193.77'

U S GOVERNMENT PRINTING OFFICE 16—62891-2

See Back (Well log incomplete)

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WELL LOG Date drilled Mar. 5, 1959

County Island -Driller Vander Steep

Owner Lynn Duncan Address

____ ¼ ____ ¼ sec. ____ T. ____ N/S R. ____ E/W.

General location:

Casing: Diam. ____ Depth ____ Open end( )
10 slot

Screen 132 ft. to 187 ft; Perforated ____ ft to ____

Water level 157 ft ~~above~~ below surface. Date 3-5-59

Bailed, ~~Pumped~~ 11 ~~GPH~~, GPM little ~~ft~~ drawdown

Material	Thickness (feet)	Depth (feet)
Topsoil, gravelly	4	4
Hardpan, gravelly	23	27
Hardpan, loose, [won't drill ahead]	10	37
Sand and gravel	13	50
Hardpan	8	58
Hardpan, gravelly	6	64
Hardpan, sandy	4	68
Hardpan, gravelly	8	76
Clay, yellow brown, [contains] with sand and small [a little] gravel	30	106

USE BACK IF NECESSARY

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WASHINGTON STATE DEPARTMENT OF ECOLOGY

Well Tagging Form

Unique Well Tag No: AGA 970

RECORD VERIFICATION (check ✓one)

☑ Well Report available (please attach this form to the well report and submit it to the Ecology Regional Office near you)

If a well report is not available, please complete a "Water Well Report for an Existing Well" form This form is available at Ecology's headquarters office **Do not use this form for wells that do not have a Water Well Report**

WELL OWNERSHIP, IF DIFFERENT FROM WELL REPORT

First Name Viewcrest Water Association Last Name

Street Address 2156 N Viewcrest Place

City Oak Harbor State WA 98277

LOCATION OF WELL, IF DIFFERENT FROM WELL REPORT

Well Address Parcel S8365-00-0000c-0, Hurley Place

City Oak Harbor County Island

T 32 N R 2 E WM Sec 3 NW/4 of the SW

Latitude ____ ____ ' ____ "

Longitude ____ ____ ' ____ "

Elevation at land surface 306 feet/meters *(circle one)*

SEE BACK SIDE OF PAGE .

RECEIVED

DEPT OF ECOLOGY

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WELL CHARACTERISTICS

Location of Well identification Tag

Strapped to well casing
(in lean-to on the back side of the pumphouse)

D	C	B	A
E	F	G	H
M	L	K	J
N	P	Q	R

Well

Scale 1 24,000 (1" = 2,000')

Indicate the location of the well within the Section by drawing a dot at that point

SECTION _____

COMMENTS